




A (x1)




B (x1)




C (x1)



D (x1)



E (x1)



F (x1)



G (x1)



H (x1)



I (x1)



J (x1)



K (x1)



L (x1)



M (x3)
M6x12



N (x1)
4mm



O (x1)
6mm



P (x1)



M-A (x4)
M4x12





M-B (x4)
M5x12




M-C (x4)
D5

1



Desktop with Existing Through-Hole.



10-55mm


6mm

10-80mm

10-60mm

10-80mm


OR




10-80mm

10-60mm

10-80mm




10-80mm



10-80mm



10-80mm




10-55mm

6mm

10-80mm


OR




10-80mm

10-60mm

10-80mm



10-80mm




10-80mm




10-80mm

2




Tighten the limiting screw (do not over tighten).




±90°

Arm can rotate 180°.




Remove or loosen the limiting screw.




±180°

Arm can rotate without stopping.


3



4



TOP



M-A
M-B
M-C